

NOTICE TO MARINERS

Musaffah Port- New buoys in ICAD area To: All Ports Users, Agents and all other concerned parties

In order to enhance safety of navigation in ICAD area within Musaffah port limits, the following three new aids to navigation buoys have been installed as below table:

Buoy ID	Туре	Color	Characteristics	Position	
				LAT.	LONG.
Lateral Marker Buoy ICAD 5	VEGA 67	Green	FL. G 3s	24° 18.712′ N	054° 27.589' E
Lateral Marker Buoy ICAD 6	VEGA 67	Green	FL. G 3s	24° 18.721′ N	054° 28.322′ E
Lateral Marker Buoy ICAD 7	VEGA 67	Green	FL.G 3s	24° 18.739′ N	054° 28.839′ E

In addition of that and refereeing to NTM 04/17, note the previous ICAD buoys have been renamed as below table:

Buoy ID	Туре	Color	Characteristics	Position	
				LAT.	LONG.
Lateral Marker Buoy ICAD 1	VEGA 67	Green	FL. G 3s	24° 18.720′ N	054° 27.115' E
Lateral Marker Buoy ICAD 2	VEGA 67	Green	FL. G 3s	24° 17.940′ N	054° 26.530' E
Lateral Marker Buoy ICAD 3	VEGA 67	Green	FL _• G 3s	24° 17.390′ N	054° 26.100′ E
Lateral Marker Buoy ICAD 4	VEGA 67	Green	FL. G 3s	24° 16.855′ N	054° 25.445′ E

Any clarification related to this Notice to Mariners may be directed to the Harbour Master.

Mariners shall adhere to all applicable rules and regulations, Harbour Master Directions and VTS instructions at all times.

Capt. Adil Banihammad Chief Harbour Master Chief Harbour Master